

---

Subject: Re: Caliber 151 - (Extra) Precision - 5 1/2 '"  
Posted by [thesnark17](#) on Mon, 06 Jul 2020 00:07:26 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

I note that while the setting is very similar and the train elements are in the same places, the holes in the base plate are not the same. Particularly the dial feet holes.

---