

---

Subject: Re: 330 Curvex

Posted by [Barney Green](#) on Sun, 04 Jan 2015 15:47:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

To me it looks like there are pins in the holes for the spring bar which hold a crimped band end. If so, you should bend the band end upen and remove the pins with pliers.

---