

---

Subject: Re: 823 Movement or Center Wheel Needed

Posted by [afire](#) on Thu, 06 Jun 2013 20:01:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Apparently the cannon pinion was fused to the original center wheel to the point that neither was salvagable.

---