Subject: Re: Gruen Mens ID

Posted by Barney Green on Fri, 01 Jul 2022 08:54:04 GMT

View Forum Message <> Reply to Message

I disagree with Jack, in my opinion most likely the hands were not Radium filled. Here a closeup of another watch with these hands, looks like the slotted hands were not filled at all:

Barney

File Attachments

1) Non luminous.JPG, downloaded 1374 times

Page 1 of 2 ---- Generated from

Vintage Gruen

