
Subject: Re: Wanted: info/source for balance staff, 1907 VE pocket watch

Posted by [Case](#) on Tue, 03 Sep 2019 17:33:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

This story is just too true to be good. Not a match; on to plan C. BTW, the only visual indicator from the top side on the stud carrier is the hole: the Madretsches has a perfectly round hole for the hairspring, while the later (non-matching) movement has semi-circle with one flat side. Difference is visible in images above.

Here's a visual of the broken staff.

Also, thinking longer term of getting this into a CAD file and finding a CM. Such a simple design. Any recos?

File Attachments

1) [1907 Balance staff \(broken\).JPG](#), downloaded 1720 times

