Subject: Re: Wanted: info/source for balance staff, 1907 VE pocket watch Posted by Case on Tue, 03 Sep 2019 17:33:43 GMT

View Forum Message <> Reply to Message

This story is just too true to be good. Not a match; on to plan C. BTW, the only visual indicator from the top side on the stud carrier is the hole: the Madretsch has a perfectly round hole for the hairspring, while the later (non-matching) movement has semi-circle with one flat side. Difference is visible in images above.

Here's a visual of the broken staff.

Also, thinking longer term of getting this into a CAD file and finding a CM. Such a simple design. Any recos?

File Attachments

1) 1907 Balance staff (broken).JPG, downloaded 2014 times

